

Mountain Valley Watch
Citizen Monitoring Report

Observation Info

Construction Stage: active construction **Date:** 08/03/2018 7:30 PM

Incident Data

Assessment Type: Pipeline Work Site


Description of potential violation

Erosion gullies , Bare soil - no mulch ,
Sediment discharge outside construction
area , Failed BMPs

Location Info

Location

Lat: 37.3202 Lon: -80.63585



Location Notes: Kow Camp road pembroke va Strong diesel smell downstream of this site.

Pictures

